Quality Control

Page 1

November 13, 2009 1:53:42 PM Item ID: D3136-041 Accept Setup Start **Revision ID:** Ε Stop Item Name: Window Assembly **Start Date:** Start Oty: 6.00 11/16/2009 **Cust Item ID:** Required Date: 11/23/2009 Req'd Qty: 6.00 **Customer:** Reference: Start Run Date: 09-11-13 Tooling: Process Plan: ______ Approvals: Date: Stop Date: _____ SPC (Y/N): Date: Sequence ID/ Operation Set Up/ Reject Draw Draw Plan Accept Reject Insp. Description Work Center ID Number Qty Qty **Run Hours** Rev. Code Number Stamp **Draw Nbr Revision Nbr** D3136 Rev E 100 0.00 FLOW WATER JET B9-11-16 Waterjet 0.00 Memo FLOW CNC Waterjet 110 QC2- Inspect parts off machine FAI/FAIB 0.00 189-11-16 0.00 Memo Quality Control 120 QC8- Inspect parts - second check 2) Sorlulic Memo

Dart Aerospace Ltd W/O: WORK ORDER CHANGES Approval Chief Eng / Prod Mgr **Approval** DATE STEP PROCEDURE CHANGE Ву **Date** Qty QC Inspector Part No: ______ PAR #: ____ Fault Category: _____ NCR: Yes No DQA: ____ Date: ____ Disposition: ____ QA: N/C Closed: ____ Date: ____ Resolution:

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC		Corrective Action Section B		Varification	Annuaval				
DATE	STEP	Section A	Initial Chief Eng			Verification A Section C	Approval Chief Eng	Approval QC Inspector			
	1					,					
						:					

Work Order ID 53727

November 13, 2009 1:53:42 PM

F.

Required Date: 11/23/2009



Page 2

Item ID:

D3136-041

Accept

Setup Start



Revision ID: Item Name:

Window Assembly

Stop

Start Date:

11/16/2009

Start Otv: 6.00 Reg'd Qty: 6.00

Cust Item ID: **Customer:**

Reference:

Approvals:

Process Plan:

Tooling: Date:

Date:

Draw

Run Start

Date: ____

SPC (Y/N):

Date:

Stop

Sequence ID/ Work Center ID

130

Thermoform Thermoforming Machine

Operation Description Set Up/ Run Hours

Draw Number Rev.

Plan Code

Accept **Qty**

Reject Reject **Qty** Number

Insp. Stamp

THERMOFORMING MACHINE

Memo

0.00

0.00

1-Thermoform as per Dwg D3136 and Folio FTA006□Dwg

Rev. E DFolio Rev.

□2- Engrave Part # and

Batch #, and affix labels □(D3108-9)

140

OC

Quality Control

QC2- Inspect parts off machine FAI/FAIB

0.00

Memo

0.00

Wh 09/11/16 K3

150

Quality Control

QC8- Inspect parts - second check

Memo

Dart	Aeros	pace	Ltd
------	--------------	------	-----

W/O:			V	VORK ORDER CHANG	ES					
DATE	STEP	PRO	CEDURE CH	IANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				****				, <u>-</u>		
Part No: PAR #:										
NCR:	_	W	ORK OR	DER NON-CONFORMA	ANCE	(NCR)			
DATE	STEP	Description of NC	Initial	Corrective Action Section B			Sign & Section C		Approval	Approval
	Section A	Section A	Chief Eng	Action Description Chief Eng		Date	Section C	Chief Eng	QC Inspector	
					:					
									1	
										
									1	
	1		1 -							

Work Order ID 53727

November 13, 2009 1:53:42 PM



Page 3

Item ID:

D3136-041

Accept

Setup Start

Stop



Revision ID:

 \mathbf{E} Window Assembly Item Name:

Start Date:

11/16/2009

Start Oty: 6.00

Required Date: 11/23/2009

Req'd Qty: 6.00



Cust Item ID:

Customer:

Draw

Number

Reference:

Approvals:

Process Plan:

Date: Tooling:

SPC (Y/N):

Date:

Date:

Draw

Rev.

Plan

Code

Start

Stop

Reject

Number

Wh 09/4/4

Reject

Qty

Run

Accept

Otv



Insp.

Stamp

Sequence ID/ Work Center ID

160

Thermoform Thermoforming Machine

Operation Description Set Up/ Run Hours

0.00

HAND FINISHING THERMOFORMING

Memo

Memo

0.00

Water sand and buff to remove scractches as required

Date:

170

OC

Quality Control

QC5- Inspect part completeness to step on W/O

Identify as per dwg & Stock Location: 216



180

Packaging Packaging

0.00

0.00

Memo

0.00

Dart	Aeros	pace	Ltd
------	--------------	------	-----

									*
W/O:			V	VORK ORDER CHANGE	S				1
DATE	DATE STEP PROCE		DURE CH	IANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						1211			
Part No: PAR #:		Fault Ca	tegory:	NCR: Yes	No DQ	A :	_ Date: _		
Resolution:			Disposit	ion:	QA: N/C CI	osed:		Date: _	
NCR:		WC	ORK OR	DER NON-CONFORMAI	NCE (NCR)			
DATE	OTED	Description of NC	Corrective Action Section B			Verification		Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date		on C	Chief Eng	QC Inspector
1	}		{					-	

Work Order ID 53727

November 13, 2009 1:53:42 PM



Page 4

Item ID:

D3136-041

Revision ID:

Item Name: Window Assembly

Е

Start Date:

11/16/2009

Start Qty: 6.00

Required Date: 11/23/2009 Req'd Qty: 6.00



Accept

Run

Setup Start

Stop



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Operation

Description

Date:

Date: _____

Tooling:

SPC (Y/N):

Set Up/

Run Hours

Date:

Date:

Plan

Accept

Reject

Start

Stop

Reject Insp.

190

Work Center ID

Sequence ID/

Quality Control

Memo

QC21- Final Inspection - Work Order Release

0.00

0.00

Number

Draw

Draw Rev.

Code

Qty

Qty

Number Stamp

Dart Aerospace Ltd

W/O:		**************************************	W	ORK ORDER CHANG	ES				
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									,
								•	
									·
Part No	:	PAR #:	Fault Cat	legory:	NCR: Ye	s No D	QA:	Date:	
Resolution:									
NCR:		\	WORK ORI	DER NON-CONFORMA	ANCE (NO	R)	**************************************		
DATE	STEP	Description of NC	Initial	Corrective Action Section Initial Action Description			ification	Approval	Approval
		Section A	Chief Eng	Chief Eng	Sigr Da		ection C	Chief Eng	QC Inspector
								į	
		,,							
			:						

Work Order ID: 53727

Parent Item:

Comments:

D3136-041RevE

Parent Item Name: Window Assembly





Start Date: 11/16/2009

Required Date: 11/23/2009

Start Qty: 6.00

Required Qty: 6.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D3108-9RevB1		Manufactured	No			100	Each	792.0000	12.0000			

Decal

Warehouse	<u>L</u> .	oc Qty	Loc Code		
Location					
Main Warehouse					
ST		792			(1) (2) (4)
34554		304		_6	DL, 08/11/16
46546		488			
	170	cf.	128 7570 26 8421		

MACRLICS.125

Purchased No

128.7570 26.8421

KB 9-11-16

1/8" Polycast II Sheet			
	Warehouse	Loc Qty	Loc Code
	Location		
	Main Warehouse		
	MAT	128.757	

110115 110633 17.2295 111711 67.7447 112888 39.7828

112885

Dart Ae	rospace l	Ltd							
W/O:			WC	ORK ORDER CHANGES					· · · · · · · · · · · · · · · · · · ·
DATE	STEP	PR	OCEDURE CHA		Ву	Date Qty	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto
Part No):	PAR #:	Fault Cate	gory: N	ICR: Yes	No DQA	\:	_ Date: _	
	Res	solution:	Disposition	n: (A: N/C CI	osed:		Date: _	
NCR:			WORK ORDI	ER NON-CONFORMANO	CE (NCF	R)			
		Description of NC		Corrective Action Section B			ation		A
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Section		Approval Chief Eng	Approva QC Inspect

DART AEROSPACE LTD	Work Order:	53727
Description: Window Assembly	Part Number:	D3136-1
Inspection Dwg: D3136 Rev: E		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

X First Article	Prototype
-----------------	-----------

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
27.50	+/-0.030	D7.√C	> Oh			
22.63	+/-0.030	23.€E	× 19h			
3.70	+/-0.030	3.70	>			
0.06	+/-0.030	.075	≫			
			,			


Measured by: B		Audited by:	2	1	Prototype Approval:	N/A
Date: 9-11-16	,	Date:	ozli	1)(4	Date:	N/A

Rev	Date	Change		Revised	βy	Appr	roved
Α	09.05.04	New Issue	P/O D3136-041	KJ/DD 9	12	\perp Δ	

Dart Aerospace Ltd

W/O:	-		ORK ORDER CHANG	ES				,,			
DATE	STEP	PRO	PROCEDURE CHANGE					Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
	<u> </u>										
· · · · · · · · · · · · · · · · · · ·											
								<u>:</u>			
Part No: PAF		PAR #:	Fault Category: NCR: Yes No DQ)QA: Date:			
Resolution:			Dispositio	n:	QA	QA: N/C Closed: Date:					
NCR:		\	WORK ORD	ER NON-CONFORM	ANCE	(NCR)				
DATE	STEP	Description of NC	Corrective Action Section				Verific	cation	Approval	Approval	
DAIL	SILF	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti		Chief Eng	QC Inspector	
				•					:		
										©	
			-								
			,								
					ļ					,	

H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE



Dart	Aeros	pace	Ltd
------	--------------	------	-----

W/O:			W	/ORK ORDER CHANG	ES				
DATE	STEP	PRO	OCEDURE CH	IANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	i c								} -
Dort No.	_	DAD #							
Part No: PAR #:									
NCR:		,		DER NON-CONFORMA					
DATE	STEP	Description of NC		Corrective Action Section B			cation	Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng	Sigr Dat		Section C	Chief Eng	QC Inspector
i									
						-			